Full Download: http://alibabadownload.com/product/operations-and-supply-chain-management-for-the-21st-century-1st-edition-bo

Chapter 2--Quality Management

Student:

1. High quality implies having the capability to consistently produce products that satisfy or exceed customer needs. True False

2. In 1979, Dr. W. Edwards Deming authored the book Quality Is Free, which emphasized that doing things right the first time adds nothing to the cost of a product or service. True False

3. External failure costs refer to the cost of poor quality if the error is caught within the production facility before it is sold to the customer. True False

4. High-quality products and services are necessary for the survival, growth, and competitiveness of an organization. True False

5. As quality increases, both internal and external failure costs decrease, whereas assurance and prevention costs increase.

True False

6. Research over a long period has shown that it is more costly to continue serving existing customers than to increase market share. True False

7. Determining the underlying components of quality is rather straightforward because quality normally means the same thing to different customers. True False

8. Like the quality of tangible goods, the quality of a service is also determined by multiple dimensions. True False

9. Perception does not influence a customer's opinion of product quality. True False

10. Craftsmen were generally in direct contact with their customers, and products were created on the basis of specifications provided by individual customers to local producers. True False

11. Inspection is the selection of randomly selected products from the production line for quality checks. True False

12. The Deming Prize is the highest honor for quality and performance excellence for a United States-based manufacturing, service, small business, education, or healthcare organization. True False

13. Feigenbaum, known as the father of modern quality management, used 14 points and the Plan-Do-Check-Act cycle to provide guidelines for implementing quality improvement plans. True False

14. A quality circle is a small group of employees who are responsible for similar or related work functions, and meets regularly to identify, analyze, and solve quality and production problems related to its work. True False

15. Robust quality principles are now routinely used in identifying the optimum design of product components for many complex industries. True False

16. TQM advocates support and commitment from the highest level of management. True False

17. The primary objective of ISO standards is to make the development, manufacturing, and supply of products and services more efficient, safe, and clean. True False

18. The U.S. government mandates ISO 9000 standards. True False

19. Total quality management (TQM) is an umbrella term that is used to describe a quality management system that addresses all areas and employees of an organization, emphasizes customer satisfaction, and uses continuous improvement tools and techniques. True False

20. The focus of ISO 14000 standards is on minimizing the harmful effects on the environment caused by an organization's activities and on achieving continual improvement in environmental performance. True False

21. The guiding framework of MBNQA is not an adequate model for implementing TQM and the teachings of quality gurus. True False

22. Visionary leadership is a central tenet of the MBNQA. True False

23. The focus of ISO 9000 standards is on minimizing the harmful effects on the environment caused by an organization's activities and on achieving continual improvement in environmental performance. True False

24. **DMAIC**, which stands for **D**efine, **M**easure, **A**nalyze, **I**mprove, and **C**ontrol, is central to Six Sigma. True False

25. Six Sigma has a genuine focus on understanding the needs and preferences of the customer. True False 26. A Six Sigma quality thus means that the distance from the mean value of the process to both the LTL and the UTL is six standard deviations. True False

27. The first three steps in the DMAIC plan are called the process characterization phase because they provide descriptive information about the existing process. True False

28. Six Sigma emphasizes the need to react to quality problems as soon as possible after they occur. True False

29. Meeting a customer's minimum standards is sufficient for a successful Six Sigma Program. True False

30. Having a customer focus is central to ISO 9000 standards, the Baldrige framework, and Six Sigma. True False

- 31. Firms undertake quality and process improvement efforts to achieve all the following goals except
- A. Cost reduction
- B. Increased market share
- C. Customer satisfaction enhancement
- D. Increased customer loyalty
- E. Improved market performance

32. Which of the following is not a broad category for the different types of costs associated with quality improvement?

- A. Internal failure costs
- B. External failure costs
- C. Inventory costs
- D. Assurance costs
- E. Prevention costs

- 33. An example of internal failure costs is
- A. Rework costs
- B. Training costs
- C. Inspection costs
- D. Sampling costs
- E. Nondestructive testing costs
- 34. An example of an assurance cost associated with the cost of quality is
- A. Rework cost
- B. Scrap costs
- C. Replacement costs
- D. Inspection costs
- E. Training costs
- 35. Which of the following is considered a "prevention cost" of quality?
- A. Cost of rework of products that failed
- B. Cost of training
- C. Cost of testing equipment used in appraisal
- D. Negative word of mouth
- E. Cost of lost production
- 36. As quality levels increase, _____.
- A. Internal costs decrease
- B. Internal costs increase
- C. External failure costs increase
- D. Assurance costs decrease
- E. Prevention costs decrease

37. In the long term, which of the following is not the result of an organization's quality improvement efforts?

- A. Higher customer satisfaction
- B. Positive word of mouth
- C. Food reputation
- D. Increased market share
- E. Employee turnover rate

- 38. Which of the following is not considered a dimension of service quality?
- A. Responsiveness
- B. Competence
- C. Access
- D. Special features
- E. Courtesy

39. A dimension of service and product quality that refers to the performance consistency of the goods or service is

- A. Responsiveness
- B. Reliability
- C. Communication
- D. Durability
- E. Serviceability

40. Which of the following is not considered a dimension of product quality?

- A. Performance
- B. Communication
- C. Reliability
- D. Durability
- E. Serviceability

41. Which term refers to a customer associating the quality of a product with the image of the company?

- A. Reputation
- B. Aesthetics
- C. Special features
- D. Durability
- E. Conformance
- 42. Security as a dimension of service quality means
- A. The willingness to assist customers
- B. Having the knowledge to perform the service
- C. Recognizing that confidentiality is important in service delivery
- D. The service provider's politeness and friendliness
- E. Physical characteristics of the service provider

- 43. Customer expectations related to quality are influenced by all the following except
- A. Personal needs
- B. Word of mouth
- C. Reputation
- D. Internal defect rates
- E. Past experience

44. Because it is impossible for a quality inspector to check each individual product to ensure that it meets the specifications, companies started using

- A. Sampling
- B. ISO quality standards
- C. 100% inspection
- D. Continuous improvement
- E. Color coding

45. The award created by the U.S. government in 1987 to help improve quality and competitiveness of U.S. companies by recognizing the highest performing organizations is the

- A. Deming Prize
- B. Malcolm Baldrige National Quality Award
- C. American Society for Quality Achievement Award
- D. Lombardi Trophy
- E. The Academy of Quality National Award

46. Which of the following concepts was not considered by Deming as an important point for quality and process improvement?

- A. Cease dependence on inspection
- B. End the practice of awarding business on the basis of the price tag
- C. Institute training on the job
- D. Eliminate slogans
- E. Reward people for doing a job correctly with a large bonus

47. Which of the following is not one of the four quality absolutes as defined by Philip Crosby?

- A. Quality is defined as conformance to requirements.
- B. The system for causing quality is prevention, not appraisal.
- C. Management must enforce quality levels.
- D. The performance standard must have zero defects.
- E. The measurement of quality is the price of nonconformance.

- 48. Which of the following is not a well-known quality guru?
- A. Adam Smith
- B. Phillip Crosby
- C. Armand Feigenbaum
- D. Joseph Juran
- E. Genichi Taguchi
- 49. Choose the statement that most closely describes a total quality management system.
- A. Detection of defects
- B. Prevention of defects
- C. Inspection for defects
- D. Conformance to specifications
- E. Correction of defects

50. A diagram that visually displays all possible causes of a quality problem with the goal of finding the reasons for the imperfections is a

- A. Deming chart
- B. Pareto diagram
- C. Quality dyad
- D. Cause-and-effect diagram
- E. PDCA cycle

51. What percentage of the area of a normal curve is between +2 and -2 standard deviations?

- A. 0%
- B. 68.3%
- C. 95.5%
- D. 99.7%
- E. 100%
- 52. When computing the process sigma, the percentage of defective products can be found by finding the area ______ in a cumulative normal distribution curve.
- A. between the UTL and LTL
- B. below the LTL
- C. beyond the LTL
- D. outside the UTL and LTL
- E. under the curve

53. In reality, on the basis of computations, a Six Sigma process quality level is equivalent to the LTL and the UTL's being how many standard deviations away from the extreme position of the mean?

- A. 1.5 standard deviations
- B. 3 standard deviations
- C. 4.5 standard deviations
- D. 6 standard deviations
- E. 12 standard deviations

54. The Six Sigma approach described in the text is implemented using a structured five-step plan known as

- A. ISO implementation procedure
- B. Deming's 14 points
- C. The Taguchi function
- D. DMAIC
- E. MBNQA
- 55. Quality improvement efforts are often credited with reducing
- A. The number of found defects
- B. Overall production costs
- C. The number of sales personnel
- D. Quality initiatives
- E. The required number of control charts
- 56. What are the four parts of the Deming cycle for continuous improvement?

57. What is a quality circle?

58. Briefly describe Dr. Edward Deming's contribution to quality.

59. What is the Malcolm Baldrige National Quality Award?

60. Describe how "managing by fact" influences TQM.

61. Describe how ISO 9000 standards can benefit consumers.

62. Discuss how customer expectations can influence the assessment of quality.

63. Describe internal failure cost, with an example in a local restaurant.

64. Sketch the cost of quality curve.

65. Identify and describe four of the dimensions of product quality discussed in the textbook.

66. For a given process, past data reveals that the mean of the process is 9 and the standard deviation is 3. Tolerance limits are specified as UTL = 16 and LTL = 2. What would the process sigma be for this process using the UTL?

67. For a given process, past data reveals that the mean of the process is 9 and the standard deviation is 3. Tolerance limits are specified as UTL = 16 and LTL = 2. What would the percent defective be for this process using the UTL?

68. A machine shop requires a specific hardness range on purchased iron blocks. A machine is used to test the hardness. To be acceptable, the hardness readings need to be between a UTL of 366 and an LTL of 335. The supplier reports that the mean hardness is 350, with a standard deviation of 7. Calculate the process sigma using the LTL.

69. A machine shop requires a specific hardness range on purchased iron blocks. A machine is used to test the hardness. To be acceptable, the hardness readings need to be between a UTL of 366 and an LTL of 335. The supplier reports that the mean hardness is 350, with a standard deviation of 7. What would the percent defective be for this process using the LTL?

70. A machine shop requires a specific hardness range on purchased iron blocks. A machine is used to test the hardness. To be acceptable, the hardness readings need to be between a UTL of 366 and an LTL of 335. The supplier reports that the mean hardness is 350, with a standard deviation of 7. The Z-score is 2.33 for a defective rate of less than 1%. What standard deviation is required if the UTL is used to compute the process sigma?

71. Pete's Pizza promises delivery to your home or office in under an hour. His goal is to deliver all Pizzas between 20 and 60 minutes. Records indicate the average delivery time is 38 minutes, with a standard deviation of 3 minutes. Is the company delivering within Six Sigma quality levels with respect to delivery time?

72. Pete's sister Patty runs a similar restaurant called Patty's Pizza with the same 1-hour delivery promise. Her delivery records show a mean delivery time of 40 minutes, with a standard deviation of 5 minutes. She does not meet Six Sigma quality levels for delivery time. What does her standard deviation need to be to achieve Six Sigma quality levels for delivery?

73. Jay Jones bought Matt's Mechanics Service. Matt told Jay that his three primary processes, diagnosis, repair and customer delivery, met internal goals 95% of the time, so he assumed customers were satisfied 95% of the time. Jay disagrees and wants to know how often customers have an error-free outcome. What would you tell him?

74. Jay decides to try to improve each process so that the percentage of error-free outcomes will be at least 95%. What will each process need to be to reach this goal?

75. The local university's Admissions' office has four steps required in the admissions process. Applications must be entered in the system, reviewed for accuracy, reviewed by the admissions team, and a letter of acceptance or rejection must be sent. To provide timely feedback, each step has a time goal. Applications are entered in the system faster than the goal 94% of the time. The accuracy review is faster than the goal 98.5% of the time. The review team only beats the goal 88.4% of the time. The letter is issued faster than the goal 99% of the time. What is the timeliness of the process?

Chapter 2--Quality Management Key

1. High quality implies having the capability to consistently produce products that satisfy or exceed customer needs.

<u>TRUE</u>

2. In 1979, Dr. W. Edwards Deming authored the book *Quality Is Free*, which emphasized that doing things right the first time adds nothing to the cost of a product or service. **FALSE**

3. External failure costs refer to the cost of poor quality if the error is caught within the production facility before it is sold to the customer.

FALSE

4. High-quality products and services are necessary for the survival, growth, and competitiveness of an organization.

<u>TRUE</u>

5. As quality increases, both internal and external failure costs decrease, whereas assurance and prevention costs increase.

TRUE

6. Research over a long period has shown that it is more costly to continue serving existing customers than to increase market share. **FALSE**

7. Determining the underlying components of quality is rather straightforward because quality normally means the same thing to different customers. **FALSE**

8. Like the quality of tangible goods, the quality of a service is also determined by multiple dimensions. **TRUE**

9. Perception does not influence a customer's opinion of product quality. **FALSE**

10. Craftsmen were generally in direct contact with their customers, and products were created on the basis of specifications provided by individual customers to local producers. **TRUE**

11. Inspection is the selection of randomly selected products from the production line for quality checks. **FALSE**

12. The Deming Prize is the highest honor for quality and performance excellence for a United States-based manufacturing, service, small business, education, or healthcare organization. **FALSE**

13. Feigenbaum, known as the father of modern quality management, used 14 points and the Plan-Do-Check-Act cycle to provide guidelines for implementing quality improvement plans. **FALSE**

14. A quality circle is a small group of employees who are responsible for similar or related work functions, and meets regularly to identify, analyze, and solve quality and production problems related to its work. **TRUE**

15. Robust quality principles are now routinely used in identifying the optimum design of product components for many complex industries.

<u>TRUE</u>

16. TQM advocates support and commitment from the highest level of management. **TRUE**

17. The primary objective of ISO standards is to make the development, manufacturing, and supply of products and services more efficient, safe, and clean. **TRUE**

18. The U.S. government mandates ISO 9000 standards. **FALSE**

19. Total quality management (TQM) is an umbrella term that is used to describe a quality management system that addresses all areas and employees of an organization, emphasizes customer satisfaction, and uses continuous improvement tools and techniques. TRUE

20. The focus of ISO 14000 standards is on minimizing the harmful effects on the environment caused by an organization's activities and on achieving continual improvement in environmental performance. **TRUE**

21. The guiding framework of MBNQA is not an adequate model for implementing TQM and the teachings of quality gurus. **FALSE**

22. Visionary leadership is a central tenet of the MBNQA. **TRUE**

23. The focus of ISO 9000 standards is on minimizing the harmful effects on the environment caused by an organization's activities and on achieving continual improvement in environmental performance. **FALSE**

24. **DMAIC**, which stands for **D**efine, **M**easure, **A**nalyze, **I**mprove, and **C**ontrol, is central to Six Sigma. **<u>TRUE</u>**

25. Six Sigma has a genuine focus on understanding the needs and preferences of the customer. **TRUE**

26. A Six Sigma quality thus means that the distance from the mean value of the process to both the LTL and the UTL is six standard deviations. **TRUE**

27. The first three steps in the DMAIC plan are called the process characterization phase because they provide descriptive information about the existing process. **TRUE**

28. Six Sigma emphasizes the need to react to quality problems as soon as possible after they occur. **FALSE**

29. Meeting a customer's minimum standards is sufficient for a successful Six Sigma Program. **FALSE**

30. Having a customer focus is central to ISO 9000 standards, the Baldrige framework, and Six Sigma. **TRUE**

- 31. Firms undertake quality and process improvement efforts to achieve all the following goals except
- A. Cost reduction
- **B.** Increased market share
- C. Customer satisfaction enhancement
- D. Increased customer loyalty
- E. Improved market performance

32. Which of the following is not a broad category for the different types of costs associated with quality improvement?

- A. Internal failure costs
- B. External failure costs
- **<u>C.</u>** Inventory costs
- D. Assurance costs
- E. Prevention costs

- 33. An example of internal failure costs is
- <u>A.</u> Rework costs
- B. Training costs
- C. Inspection costs
- D. Sampling costs
- E. Nondestructive testing costs
- 34. An example of an assurance cost associated with the cost of quality is
- A. Rework cost
- B. Scrap costs
- C. Replacement costs
- **D.** Inspection costs
- E. Training costs
- 35. Which of the following is considered a "prevention cost" of quality?
- A. Cost of rework of products that failed
- **<u>B.</u>** Cost of training
- C. Cost of testing equipment used in appraisal
- D. Negative word of mouth
- E. Cost of lost production
- 36. As quality levels increase, _____.
- <u>A.</u> Internal costs decrease
- B. Internal costs increase
- C. External failure costs increase
- D. Assurance costs decrease
- E. Prevention costs decrease

37. In the long term, which of the following is not the result of an organization's quality improvement efforts?

- A. Higher customer satisfaction
- B. Positive word of mouth
- C. Food reputation
- D. Increased market share
- **E.** Employee turnover rate

- 38. Which of the following is not considered a dimension of service quality?
- A. Responsiveness
- B. Competence
- C. Access
- **<u>D.</u>** Special features
- $E. \ Courtesy$

39. A dimension of service and product quality that refers to the performance consistency of the goods or service is

- A. Responsiveness
- **<u>B.</u>** Reliability
- C. Communication
- D. Durability
- E. Serviceability

40. Which of the following is not considered a dimension of product quality?

- A. Performance
- **<u>B.</u>** Communication
- C. Reliability
- D. Durability
- E. Serviceability

41. Which term refers to a customer associating the quality of a product with the image of the company?

- A. Reputation
- B. Aesthetics
- C. Special features
- D. Durability
- E. Conformance
- 42. Security as a dimension of service quality means
- A. The willingness to assist customers
- B. Having the knowledge to perform the service
- C. Recognizing that confidentiality is important in service delivery
- D. The service provider's politeness and friendliness
- E. Physical characteristics of the service provider

- 43. Customer expectations related to quality are influenced by all the following except
- A. Personal needs
- B. Word of mouth
- C. Reputation
- **<u>D.</u>** Internal defect rates
- E. Past experience

44. Because it is impossible for a quality inspector to check each individual product to ensure that it meets the specifications, companies started using

- <u>A.</u> Sampling
- B. ISO quality standards
- C. 100% inspection
- D. Continuous improvement
- E. Color coding

45. The award created by the U.S. government in 1987 to help improve quality and competitiveness of U.S. companies by recognizing the highest performing organizations is the

- A. Deming Prize
- B. Malcolm Baldrige National Quality Award
- C. American Society for Quality Achievement Award
- D. Lombardi Trophy
- E. The Academy of Quality National Award

46. Which of the following concepts was not considered by Deming as an important point for quality and process improvement?

- A. Cease dependence on inspection
- B. End the practice of awarding business on the basis of the price tag
- C. Institute training on the job
- D. Eliminate slogans
- **<u>E.</u>** Reward people for doing a job correctly with a large bonus

47. Which of the following is not one of the four quality absolutes as defined by Philip Crosby?

- A. Quality is defined as conformance to requirements.
- B. The system for causing quality is prevention, not appraisal.
- <u>C.</u> Management must enforce quality levels.
- D. The performance standard must have zero defects.
- E. The measurement of quality is the price of nonconformance.

- 48. Which of the following is not a well-known quality guru?
- A. Adam Smith
- B. Phillip Crosby
- C. Armand Feigenbaum
- D. Joseph Juran
- E. Genichi Taguchi
- 49. Choose the statement that most closely describes a total quality management system.
- A. Detection of defects
- **<u>B.</u>** Prevention of defects
- C. Inspection for defects
- D. Conformance to specifications
- E. Correction of defects

50. A diagram that visually displays all possible causes of a quality problem with the goal of finding the reasons for the imperfections is a

- A. Deming chart
- B. Pareto diagram
- C. Quality dyad
- $\underline{\mathbf{D.}}$ Cause-and-effect diagram
- E. PDCA cycle
- 51. What percentage of the area of a normal curve is between +2 and -2 standard deviations?
- A. 0%
- B. 68.3%
- <u>C.</u> 95.5%
- D. 99.7%
- E. 100%
- 52. When computing the process sigma, the percentage of defective products can be found by finding the area ______ in a cumulative normal distribution curve.
- A. between the UTL and LTL
- B. below the LTL
- <u>**C.</u>** beyond the LTL</u>
- D. outside the UTL and LTL
- E. under the curve

53. In reality, on the basis of computations, a Six Sigma process quality level is equivalent to the LTL and the UTL's being how many standard deviations away from the extreme position of the mean?

- A. 1.5 standard deviations
- B. 3 standard deviations
- <u>C.</u> 4.5 standard deviations
- D. 6 standard deviations
- E. 12 standard deviations

54. The Six Sigma approach described in the text is implemented using a structured five-step plan known as

- A. ISO implementation procedure
- B. Deming's 14 points
- C. The Taguchi function
- <u>**D.</u> DMAIC**</u>
- E. MBNQA
- 55. Quality improvement efforts are often credited with reducing
- A. The number of found defects
- **<u>B.</u>** Overall production costs
- C. The number of sales personnel
- D. Quality initiatives
- E. The required number of control charts
- 56. What are the four parts of the Deming cycle for continuous improvement?

Plan, Do, Check, Act

57. What is a quality circle?

A quality circle is a small group of employees who are responsible for similar or related work functions. This volunteer group meets regularly to identify, analyze, and solve quality and production problems related to its work.

58. Briefly describe Dr. Edward Deming's contribution to quality.

Deming is often considered the father of modern quality management. He emphasized the philosophy of continuous improvement. He taught that the quest for quality is a never-ending journey. Deming also created simple-to-understand examples and visuals for teaching quality management concepts. For example, he summarized his teachings in 14 points, which continue to be used as a guide for quality management by practicing managers (see Table 2.1). He summarized his continuous improvement philosophy using a simple diagram of a wheel with four activities: Plan, Do, Check, and Act (see Figure 2.5). Deming was also instrumental in teaching statistical quality control (SQC) to managers.

59. What is the Malcolm Baldrige National Quality Award?

It was created by the U.S. government in 1987 to help improve the quality and competitiveness of U.S. companies by recognizing the highest-performing organizations in the manufacturing, service, health-care, education, and small business categories.

60. Describe how "managing by fact" influences TQM.

TQM emphasizes the need for using objective data rather than subjective perceptions when making managerial decisions. It advocates the use of statistical techniques such as statistical process control and the design of experiments for collecting and analyzing data.

61. Describe how ISO 9000 standards can benefit consumers.

For consumers, conformity of products and services to international standards provides assurance of the quality, safety, and reliability of those products and services.

62. Discuss how customer expectations can influence the assessment of quality.

Customer expectations are influenced by many different factors, such as personal needs, word of mouth or the reputation of the company, and individuals' own past experiences. Therefore, a customer compares the objective quality of a product based on the dimensions described earlier with his or her expectations. Based on such comparisons, the perceived quality of the product is thought to be higher or lower than expectations. Therefore, quality excellence means improving the dimensions of both objective and perceived product quality.

63. Describe internal failure cost, with an example in a local restaurant.

If a defective good (or service) is produced but the error is caught before the product leaves the production facility, then all costs associated with rework, scrap, and lost production time are classified as internal failure cost. For example, suppose that a customer ordered a thin-crust pizza with only vegetarian toppings. Let us assume that the pizza delivery company made a mistake in the order-taking process and produced a pizza with a thick crust and a pepperoni topping, but caught this mistake before the driver could deliver the pizza to the customer. All the costs associated with this mistake (i.e., the waste of a fully cooked pizza and the equipment and employee time used in the production of the wrong pizza) will be classified in the internal failure cost category.

64. Sketch the cost of quality curve.



- *Performance*. This refers to the primary purpose of a tangible good.
- Special features. Special features are additional characteristics of a tangible good that enhance the value or usefulness of the primary purpose of the product.
- *Reliability*. Consistency in the performance of a good is measured by its reliability. A good with higher reliability is considered to have higher quality than a good with lower reliability.
- *Conformance*. Conformance is the degree to which a good matches the prespecified standards or guidelines.
- · *Durability*. Durability refers to the useful life of a good. The longer the useful life, the higher the quality.
- Serviceability. The ability of the good to perform with ease is also a measure of its quality.
- Aesthetics. A good's appearance is often considered to be a dimension of its quality.
- Brand equity or reputation. Often customers associate the quality of a good with the image of the company, its brand name, or its past reputation. These indirect measures of quality are collectively called brand equity.

66. For a given process, past data reveals that the mean of the process is 9 and the standard deviation is 3. Tolerance limits are specified as UTL = 16 and LTL = 2. What would the process sigma be for this process using the UTL?

$$\frac{16-9}{3} = 2.33$$

67. For a given process, past data reveals that the mean of the process is 9 and the standard deviation is 3. Tolerance limits are specified as UTL = 16 and LTL = 2. What would the percent defective be for this process using the UTL?

This solution will vary depending on the area under the standard normal curve table that is used in the book. Using a table that provides the area to the left of the z-score, you will have the following solution: P(Z = 2.33) = 0.9901 (using the table) The problem is asking for the area to the right of 2.33. Percentage of defective products = (1 - 0.9901) * 100% = 0.9%

68. A machine shop requires a specific hardness range on purchased iron blocks. A machine is used to test the hardness. To be acceptable, the hardness readings need to be between a UTL of 366 and an LTL of 335. The supplier reports that the mean hardness is 350, with a standard deviation of 7. Calculate the process sigma using the LTL.

sigma =
$$\frac{350 - 335}{7}$$
 = 2.14

Process

69. A machine shop requires a specific hardness range on purchased iron blocks. A machine is used to test the hardness. To be acceptable, the hardness readings need to be between a UTL of 366 and an LTL of 335. The supplier reports that the mean hardness is 350, with a standard deviation of 7. What would the percent defective be for this process using the LTL?

P(Z = 2.14) = 0.9901 (using the table) The problem is asking for the area to the right of 2.14: percent defective products = (1 - 0.9838) * 100% = 1.62%

70. A machine shop requires a specific hardness range on purchased iron blocks. A machine is used to test the hardness. To be acceptable, the hardness readings need to be between a UTL of 366 and an LTL of 335. The supplier reports that the mean hardness is 350, with a standard deviation of 7. The Z-score is 2.33 for a defective rate of less than 1%. What standard deviation is required if the UTL is used to compute the process sigma?

Process sigma = $\frac{366 - 350}{\sigma}$ = 2.33 Standard deviation = $\frac{16}{2.33}$ = 6.87

71. Pete's Pizza promises delivery to your home or office in under an hour. His goal is to deliver all Pizzas between 20 and 60 minutes. Records indicate the average delivery time is 38 minutes, with a standard deviation of 3 minutes. Is the company delivering within Six Sigma quality levels with respect to delivery time?

Actual upper (mean + 6*s) value = 38 + 6*3 = 56Actual lower (mean + 6*s) value = 38 - 6*3 = 20Yes, the promised time is within 6 standard deviations of the mean.

72. Pete's sister Patty runs a similar restaurant called Patty's Pizza with the same 1-hour delivery promise. Her delivery records show a mean delivery time of 40 minutes, with a standard deviation of 5 minutes. She does not meet Six Sigma quality levels for delivery time. What does her standard deviation need to be to achieve Six Sigma quality levels for delivery?

The distance from the mean to either the LTL or the UTL is 20 minutes. To achieve Six Sigma Quality levels, 6 * s needs to equal 20.

6* s = 20; s = 3.33

Operations and Supply Chain Management for the 21st Century 1st Edition Boyer Test Bank

Full Download: http://alibabadownload.com/product/operations-and-supply-chain-management-for-the-21st-century-1st-edition-bo

73. Jay Jones bought Matt's Mechanics Service. Matt told Jay that his three primary processes, diagnosis, repair and customer delivery, met internal goals 95% of the time, so he assumed customers were satisfied 95% of the time. Jay disagrees and wants to know how often customers have an error-free outcome. What would you tell him?

0.95 * 0.95 * 0.95 = 0.8574 = 85.74% error-free outcomes

74. Jay decides to try to improve each process so that the percentage of error-free outcomes will be at least 95%. What will each process need to be to reach this goal?

Process 1 * Process 2 * Process 3 = 0.95 Process³ = 0.95 Process = $0.95^{0.33} = 0.9830$ Each process will have to be error free 98.3% of the time for the outcome to be error free 95% of the time.

75. The local university's Admissions' office has four steps required in the admissions process. Applications must be entered in the system, reviewed for accuracy, reviewed by the admissions team, and a letter of acceptance or rejection must be sent. To provide timely feedback, each step has a time goal. Applications are entered in the system faster than the goal 94% of the time. The accuracy review is faster than the goal 98.5% of the time. The review team only beats the goal 88.4% of the time. The letter is issued faster than the goal 99% of the time. What is the timeliness of the process?

0.94 * 0.985 * 0.884 * 0.99 = 0.8103, or 81.03% of the time